

**875—75.1(89A) New installations.**

**75.1(1)** Installation inspection and permit fees for elevators shall be as follows: up to and including four landings—\$500; five or more landings—\$600. Installation inspection and permit fees for escalators and moving walks shall be \$500. These fees include initial inspection and first-year operating permit. If the conveyance does not comply at the time of the acceptance inspection and has to be reinspected through no fault of the division of labor services, there shall be a reinspection fee of \$200 for each additional inspection. The installation inspection and permit fees shall be remitted to the division of labor services when the application is filed.

Consultative inspections may be performed at the discretion of the labor commissioner for a fee of \$100 per hour, including travel time, with a minimum charge of \$200.

**75.1(2)** Installation inspection and permit fees for dumbwaiters and inclined or vertical wheelchair lifts shall be \$350. These fees include initial inspection and first-year permit. If the conveyance does not comply at the time of the acceptance inspection and has to be reinspected through no fault of the division of labor services, there shall be a reinspection fee of \$200 for each additional inspection. The installation inspection and permit fees shall be remitted to the division of labor services when the application is filed.

Consultative inspections may be performed at the discretion of the labor commissioner for a fee of \$100 per hour, including travel time, with a minimum charge of \$200.

**75.1(3)** Installation inspection and permit fees for each wind tower lift as described in rule 875—72.12(89A) shall be \$250. This fee includes the initial inspection; the first-year operating permit; and the issuance of a single installation permit for all of the identical wind tower lifts installed in identical wind towers in a single wind farm as the result of one construction contract. This fee is applicable to all wind tower lifts regardless of the date of installation. If a wind tower lift is not in compliance at the time of the installation inspection and has to be reinspected through no fault of the division of labor services, there shall be a reinspection fee of \$150 for each additional inspection.

**75.1(4)** The cost of reviewing sectional plans or prints once is included in the above fees. Print revisions submitted to the division shall be subject to an additional fee of \$50.